

# Sample Fire Report

Street Address  
City, State, Zip

Prepared for: Your Client Name Here

Prepared by: Your Company Name Here

1234 Any Street

Anywhere, US 12345

Incident Date: 7/15/05

Restoration Completion: 11/7/05

Date: 11/20/05

Time: 12:00pm

Sample Fire Report



Location: Exterior

Room: Patio Area off Kitchen and Storage Room

Loss: Extensive Damage

Equipment: Digital Camera

Problem

Extensive structural damage to the homes ceiling joist and rafter systems was evident. Structural repairs were required to reinforce weakened roof structure. Smoke and water damage was moderate and required water extraction cleaning, sealing. Exterior finishes of siding, trim, soffits and ceilings required total replacement.

Sample Fire Report



Location: Interior 1st Floor

Room: Kitchen

Loss: Moderate

Equipment: Digital camera

Problem

Fire originated from faulty electrical outlet (highlighted) behind cooking range. Fire was isolated quickly with minimal structural damage to the load bearing exterior wood framed wall. Fire damaged the cabinetry beyond salvage. Walls, ceiling and floors all sustained water and smoke damage.

Sample Fire Report



Location: Interior 1st Floor

Room: Bathroom

Loss: Moderate

Equipment: Digital Camera

Problem

Fire originated at faulty curling iron on vanity cabinet (location referenced). Fire damage was minimal with mostly smoke damage. Bath required water extraction, cleaning and sealing. Fixtures were replaced.

Floor tile was salvaged but required cleaning.

**Sample Fire Report Summary**

Location:Exterior - Room:Patio Area off Kitchen and Storage Room - Loss:Extensive Damage  
Equipment: Digital Camera  
Problem: Extensive structural damage to the homes ceiling joist and rafter systems was evident. Structural repairs were required to reinforce weakened roof structure. Smoke and water damage was moderate and required water extraction cleaning, sealing. Exterior finishes of siding, trim, soffits and ceilings required total replacement.

Location:Interior 1st Floor - Room:Kitchen - Loss:Moderate  
Equipment: Digital camera  
Problem: Fire originated from faulty electrical outlet (highlighted) behind cooking range. Fire was isolated quickly with minimal structural damage to the load bearing exterior wood framed wall. Fire damaged the cabinetry beyond salvage. Walls, ceiling and floors all sustained water and smoke damage.

Location:Interior 1st Floor - Room:Bathroom - Loss:Moderate  
Equipment: Digital Camera  
Problem: Fire originated at faulty curling iron on vanity cabinet(locaton referanced). Fire damage was minimal with mostly smoke damage. Bath required water extraction, cleaning and sealing. Fixtures were replaced. Floor tile was salvaged but required cleaning.