


Sample Forensic Report




1234 Madison Rd.
Anywhere, US 12345

Prepared for: John Smith

Prepared by: Your Company Name Here
1234 Some Street
Somewhere, US 12345
We See What You're Missing


Date: July 7, 2005
Time: 7:17 am
Ambient Temperature: 45*
Wind Speed: 2.5 mph
Relative Humidity: 30*

Sample Forensic Report



Floor: Interior
Location: 2nd Floor
Equipment: Flir ThermaCAM B2


Concerns:
Water damage detected from toilet leaking condition. Corrections are required to floor system including dry out and sanitizing.



Floor: Interior
Location: Storage room
Equipment: Flir ThermaCAM B2

Concerns:
Water intrusion confirmed, Investigate and perform appropriate repair.

Sample Forensic Report



Floor: Interior
Location: Master Closet
Orientation: South exterior wall
Equipment: Flir ThermaCAM B2

Concerns:
Noted in-floor convection heating system.



Floor: Interior
Location: Living Room
Orientation: South Exterior Wall
Equipment: Flir ThermaCAM B2


Concerns:
Insulation missing in wall cavity

Sample Forensic Report



Floor: Exterior
Location: Rear
Orientation: South Exterior
Equipment: Flir ThermaCAM B2


Concerns:
Mortar missing in wall brick cavities



Floor: Interior
Location: Bathroom 2nd Floor
Equipment: Flir ThermaCAM B2

Concerns:
Water intrusion confirmed, Investigate and perform appropriate repair.

Sample Forensic Report



Floor: Exterior
 Location: Living Room Window
 Orientation: South wall
 Equipment: Flir ThermaCAM B2

Concerns:
 Insulation missing in wall cavity



The Global Leader in Infrared Cameras

Concerns:
 Photos Courtesy of Flir Thermography.

Sample Forensic ReportSummary

Floor:Interior - Location2nd Floor

Equipment: Flir ThermaCAM B2

Problem: Water damage detected from toilet leaking condition. Corrections are required to floor system including dry out and sanitizing.

Floor:Interior - LocationStorage room

Equipment: Flir ThermaCAM B2

Problem: Water intrusion confirmed, Investigate and perform appropriate repair.

Floor:Interior - LocationMaster Closet - Orientation:South exterior wall

Equipment: Flir ThermaCAM B2

Problem: Noted in-floor convection heating system.

Floor:Interior - LocationLiving Room - Orientation:South Exterior Wall

Equipment: Flir ThermaCAM B2

Problem: Insulation missing in wall cavity

Floor:Exterior - LocationRear - Orientation:South Exterior

Equipment: Flir ThermaCAM B2

Problem: Mortar missing in wall brick cavities

Floor:Interior - LocationBathroom 2nd Floor

Equipment: Flir ThermaCAM B2

Problem: Water intrusion confirmed, Investigate and perform appropriate repair.

Floor:Exterior - LocationLiving Room Window - Orientation:South wall

Equipment: Flir ThermaCAM B2

Problem: Insulation missing in wall cavity

Problem: Photos Courtesy of Flir Thermography.