



Your Company Name Here
1234 Some Street
Somewhere, US 12345
We See What You're Missing


Sample Energy Audit Report



5432 Anywhere St.
Somewhere, US 12345



Date:8/15/05
Time:8:00-10:30 am
Ambient Temperature:46 degrees
Wind Speed:2.5 mph
Relative Humidity:45%

Sample Energy Audit Report



Floor: 2nd Floor
Location: Bedroom Closet
Orientation: South
Equipment: Flir B2

Concerns:
In floor heating system shown



Floor: 1st Floor
Location: Living Room
Orientation: East
Equipment: Flir B2


Concerns:
Noted voids in thermal insulated wall areas

Sample Energy Audit Report



Floor: 2nd Floor
Location: Bedroom #2
Orientation: East
Equipment: Flir B2


Concerns:
Noted voids in thermal insulated wall areas.



Floor: 2nd Floor
Location: Bedroom#2
Orientation: East
Equipment: Flir B2


Concerns:
Noted voids in thermal insulated stud wall cavity. Corrections are recommended.

Sample Energy Audit Report



Floor: 2nd Floor
Location: Bedroom #2
Orientation: East
Equipment: Flir B2

Concerns:
Noted voids in thermal insulated stud wall cavity. Corrections are recommended.



Floor: 2nd Floor
Location: Office
Orientation: Southwest
Equipment: Flir B2


Concerns:
Shot showing the EZmark zoom feature. DUAL-VIEW can also annotate your images using arrows and ellipses!

Sample Energy Audit Report



Floor: 1st Floor
Location: Living Room
Orientation: South
Equipment: Flir B2

Concerns:
Noted voids in thermal insulated stud wall cavity. Corrections are recommended.



Floor: 1st Floor
Location: Living Room
Orientation: North
Equipment: Flir B2

Concerns:
Further investigation of wall cavity is recommended due to anomaly detected.

Sample Energy Audit Report Summary

Floor:2nd Floor - LocationBedroom Closet - Orientation:South
Equipment: Flir B2
Problem: In floor heating system shown

Floor:1st Floor - LocationLiving Room - Orientation:East
Equipment: Flir B2
Problem: Noted voids in thermal insulated wall areas

Floor:2nd Floor - LocationBedroom #2 - Orientation:East
Equipment: Flir B2
Problem: Noted voids in thermal insulated wall areas.

Floor:2nd Floor - LocationBedroom#2 - Orientation:East
Equipment: Flir B2
Problem: Noted voids in thermal insulated stud wall cavity. Corrections are recommended.

Floor:2nd Floor - LocationBedroom #2 - Orientation:East
Equipment: Flir B2
Problem: Noted voids in thermal insulated stud wall cavity. Corrections are recommended.

Floor:2nd Floor - LocationOffice - Orientation:Southwest
Equipment: Flir B2
Problem: Shot showing the EZmark zoom feature. DUAL-VIEW can also annotate your images using arrows and ellipses!

Floor:1st Floor - LocationLiving Room - Orientation:South
Equipment: Flir B2
Problem: Noted voids in thermal insulated stud wall cavity. Corrections are recommended.

Floor:1st Floor - LocationLiving Room - Orientation:North
Equipment: Flir B2
Problem: Further investigation of wall cavity is recommended due to anomaly detected.