

Thermal Evaluation




1234 Madison Rd.
Anywhere, US 12345

Prepared for: John Smith

Prepared by: Your Company Name Here
1234 Any Street
Anywhere, US 12345
Visual report of findings.
Energy losses and moisture infiltration.

Date: July 7, 2005
Time: 7:17 am
Ambient Temperature: 45*
Wind Speed: 2.5 mph
Relative Humidity: 30*


Thermal Evaluation



Location Floor: Interior
Location Room: 2nd Floor
Equipment: Flir ThermaCAM B2

Observations:

Water damage detected from toilet leaking condition. Corrections are required to floor system including dry out and sanitizing.




Location Floor: Interior
Location Room: Storage room
Equipment: Flir ThermaCAM B2

Observations:

Water intrusion confirmed, Investigate and perform appropriate repair.


Thermal Evaluation



Location Floor: Interior
Location Room: Master Closet
Location Direction: South exterior wall
Equipment: Flir ThermaCAM B2

Observations:

Insulation missing in wall cavity below window. Also noted in-floor convection heating system.




Location Floor: Interior
Location Room: Living Room
Location Direction: South Exterior Wall
Equipment: Flir ThermaCAM B2

Observations:


Insulation missing in wall cavity

Thermal Evaluation



Location Floor: Exterior
Location Room: Rear
Location Direction: South Exterior
Equipment: Flir ThermaCAM B2


Observations:
Mortar missing in wall brick cavities



Location Floor: Interior
Location Room: Bathroom 2nd Floor
Equipment: Flir ThermaCAM B2

Observations:
Water intrusion confirmed, Investigate and perform appropriate repair.

Thermal Evaluation



Location Floor: Exterior
Location Room: Living Room Window
Location Direction: South wall
Equipment: Flir ThermaCAM B2

Observations:
Insulation missing in wall cavity



The Global Leader in Infrared Cameras

Observations:
Photos Courtesy of Flir Thermography.

Thermal Evaluation Summary

Location Floor:Interior - Location Room:2nd Floor

Equipment: Flir ThermaCAM B2

Problem: Water damage detected from toilet leaking condition. Corrections are required to floor system including dry out and sanitizing.

Location Floor:Interior - Location Room:Storage room

Equipment: Flir ThermaCAM B2

Problem: Water intrusion confirmed, Investigate and perform appropriate repair.

Location Floor:Interior - Location Room:Master Closet - Location Direction:South exterior wall

Equipment: Flir ThermaCAM B2

Problem: Insulation missing in wall cavity below window. Also noted in-floor convection heating system.

Location Floor:Interior - Location Room:Living Room - Location Direction:South Exterior Wall

Equipment: Flir ThermaCAM B2

Problem: Insulation missing in wall cavity

Location Floor:Exterior - Location Room:Rear - Location Direction:South Exterior

Equipment: Flir ThermaCAM B2

Problem: Mortar missing in wall brick cavities

Location Floor:Interior - Location Room:Bathroom 2nd Floor

Equipment: Flir ThermaCAM B2

Problem: Water intrusion confirmed, Investigate and perform appropriate repair.

Location Floor:Exterior - Location Room:Living Room Window - Location Direction:South wall

Equipment: Flir ThermaCAM B2

Problem: Insulation missing in wall cavity

Problem: Photos Courtesy of Flir Thermography.